

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

ID#	# Sample Location			рН	Alk	PO4	Sili	Y/N	<has sample<="" th=""><th>County: Lincoln Agency: REGIO</th></has>	County: Lincoln Agency: REGIO		
1	77 58	<del>-</del> (	YUD	7.1	35	4		Y	met the minimum(s)?	DISTRIBUTION		
	,	<del></del>							PWS ID 4100564			
		************		-					BAY HILLS WATER ASSOCIATION			
									Sample Period = $\frac{Ja Ly}{ZZ}$ Month/Year			
									Sample Frequency: Every 36 months			
									Distribution Samples required: 1			
									Number of excursions during this  Sample Period =O  (Number of locations when any WQP was less than the minimum.)  Note: Entry Point and Distribution  Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.			
								ļ				
									Reference			
									Minima	ım Water Quality		
										eters as set by State:		
				-					рН	7.0		
										0		
<u> </u>					ļ							
(N = No = Excursion) Total N's												
Sic	Print Name: John Mackown  Signature: John Mackown  Date: 7-12-22											
	Send to Drinking Water Program within 10 days after end of sampling period											

Send/to Drinking Water Program within 10 days after end of sampling period DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp