Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

County: V	<< Have	Y/N	Other	Phos	Alk	рН	Day
	minimums		OFF				1
	been met for		OFF				2
	this day?		OFF				3
			OFF				4
			OFF				5
P	1		OFF				6
Ti	1		OFF				7
Cample newleds	1		OFF				8
Sample period:			OFF				9
umber of excursio] N		OFF				10
]		OFF				11
cursions in 6 mon	Over 9 exc		OFF				12
excursions are o			OFF				13
ch the water qua	1		OFF				14
et by the State.	minimum s		OFF				15
			OFF				16
e	Referenc		OFF				17
			OFF				18
Minimum Wa			OFF				19
Parameter(s)] [OFF				20
			OFF				21
pH TBD			OFF				22
			OFF				23
PO4 0.4			OFF				24
			OFF				25
Assessme			OFF				26
			OFF				27
: Larry McCollum	Print Name		OFF				28
CONTA	Signature:_		OFF				29
100	Jigilature:_		OFF				30
ne: 06 Apr 2021;	Date & Pho		OFF				31
		-	State of the state		25 77.77		

Well inspected daily. Samples collected when well is operating at time of inspection NR = Well not running during inspection

(No = N = Excursion)

Total N's

Wasco Agency: REGION 1

> **Lone Pine Well ENTRY POINT**

EP-B PWS ID 41-00869

HE DALLES, CITY OF

March 2021

ons during this month:

ths is a violation. Entry Point and cumulative). An 'excursion' is any ality parameter(s) fall below the

Reference	
	Minimum Water Quality Parameter(s) as set by the State:
	pH TBD
1	PO4 0.4 (Orthophosphate)
	Assessment Monitoring

541-298-2248 x 5000

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp