

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

ID #	Sample Location	pH .	Alk	PO4	Sili	Y/N	<has sample<="" th=""><th rowspan="2">DISTRIBUTION</th></has>	DISTRIBUTION	
	entry pout distribu	7.6	26			y	met the minimums?		
	Site #1	7.6				У	minimonis.		
	Site #6	7.5	20			У	PW	S ID 4100926	
1					H	Н	WALDPORT, CITY OF Sample Period: Every 36 months		
								# of Distribution Samples required:	
						Н			
						H	Number of excursions during this Sample Period: (Count the number of locations when any WQP was less than the minimum.)		
E									
							Note: Entry Point and Distribution Excursions are cumulative. Add Entr Point and Distribution Excursions to get total for sample period.		
Н							Reference		
								n Water Quality ers as set by State:	
_							pH 7	7.2	
							_		
	(N = No =	Even		Tata	I NP-	0	=	- 1	
D.					1.	×		_	
	Print Name: Late T. Arrent Signature: July Dat						Do	rte: 09/07/23	
		о ОН	D wit	hin 1	0 day	s afte	r end of sampling		

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381