

vvater Quality rarameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	
1	7.5				Y	b
2	7,5			`\	Y	fo
3	7,6				Y	
4	7.5				1 Y	
5	7.5				Y	
6	7.4				Y	
789	7,5				17	
8	7.4				Y	
	7,5				1	
10	7.6	20			1	
11/12	7.5	20			7	
13					1	
14	7.5				7	
15	7.5				1	
16	7.6				1/.	
17	7,6				4	
18	7.5				4	
19	7.5				14	
19 20 21	7.5				4	
21	7.5				Ý	
22	7.5				14	
23	7.5	22			4	
24	7,4				7	
25	7.4				4	
26	7.4				4	
70	7.4				4	
28	1.6				1	
				Architecture and a second		
	-					
						1

(No = N = Excursion) Total N's

<<Have minimums been met for this day?

ENTRY POINT A

PWS ID 4100926
WALDPORT, CITY OF

Sample perio	d:	02/21
	,	Month/Year
	ber of days w	ing this month: when any WQP was les
(Over 9 excursion	ons in 6 mont bution excurs	e previous 5 months:_ ths is a violation. Entry sions are cumulative) Y/N
-Reference)	
	linimum Wat arameters as	ter Quality s set by State:
: :- ::	pH 7.2	
Print Name:_	Lyle T.	Arrant
Signature:	July L. A	Chrant
Date: 03/03	121	1 -6 11
end to OHD withi	n 10 days aft	er end of sampling pe

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-438