)'(DHS

Oregon Department of Human Services

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N	<<Have minimums been met for this day?
1	7.8	N/A	N/A	N/A	YES	
2	7.8	N/A	N/A	N/A	YES	
3	7.7	N/A	N/A	N/A	YES	
4	7.8	N/A	N/A	N/A	YES	
5	7.8	N/A	N/A	N/A	YES	
6	7.6	N/A	N/A	N/A	YES	
7	7.6	N/A	N/A	N/A	YES	
8	7.6	N/A	N/A	N/A	YES	
9	7.6	N/A	N/A	N/A	YES	
10	7.6	N/A	N/A	N/A	YES	
11	7.5	N/A	N/A	N/A	YES	
12	7.6	N/A	N/A	N/A	YES	
13	7.5	N/A	N/A	N/A	YES	
14	7.5	N/A	N/A	N/A	YES	
15	7.5	N/A	N/A	N/A	YES	
16	7.5	N/A	N/A	N/A	YES	
17	7.6	N/A	N/A	N/A	YES	
18	7.5	N/A	N/A	N/A	YES	
19	7.6	N/A	N/A	N/A	YES	
20	7.5	N/A	N/A	N/A	YES	
21	7.5	N/A	N/A	N/A	YES	
22	7.5	N/A	N/A	N/A	YES	
23	7.5	N/A	N/A	N/A	YES	
24	7.5	N/A	N/A	N/A	YES	
25	7.5	N/A	N/A	N/A	YES	
26	7.5	N/A	N/A	N/A	YES	
27	7.4	N/A	N/A	N/A	YES	
28	7.4	N/A	N/A	N/A	YES	
29	7.4	N/A	N/A	N/A	YES	
30	7.4	N/A	N/A	N/A	YES	
31	7.4	N/A	N/A	N/A	YES	
(No=N=Excursion)			Total N's			Send to DWP within 10 days after end of sampling period

County: Lane

Agency: REGION 2

ENTRY POINT

Entry Point: EP-B

PWS ID 4100246B

System Name: **Creswell, City of**

Sample period: **May-21**

Month/year

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimun *set by the State.*

Reference: Minimun pH set on 11/3/2003 By John Potts.

Minimum Water Quality Parameter(s) as set by State:

pH	**7.1**	
Alk	N/A	*(Alkalinity)*
PO4	N/A	*(Orthophosphate)*
Sili	N/A	*(Silicate)*

Print Name: **Mike Howard**

Signature: ***Mike Howard***

541-736-6015

6/3/2021