Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

DHS oregon department of human services

Date ~~ID #~~	Sample Location	pH	Alk	PO4	Sili	Y/N
8/1		7.4				Y
8/4		7.4				Y
8/8		7.4				Y
8/11		7.5				Y
8/15		7.4				Y
8/18		7.4				Y
8/22		7.4				Y
8/25		7.5				Y
8/29		7.4				Y

(N = No = Excursion) **Total N's** Ø

<Has sample met the minimum(s)?

County: Linn Agency: C

DISTRIBUTION

PWS ID 4100474

LAWRENCE SUBDIVISION WTR.ASSN.

Sample Period = August/2022 *Month/Year*

Sample Frequency: Every 12 months

Distribution Samples required: 1

Number of excursions during this Sample Period = Ø

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

Reference

Minimum Water Quality Parameters as set by State:

pH 7.2

Print Name: Jody Anthony

Signature: Jody Anthony **Date:** 9/9/2022

Send to Drinking Water Program within 10 days after end of sampling period
DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp