Water Quality Parameter Monitoring Form

# Lead & Copper Rule Corrosion Control

DHS oregon department of human services

| Day | pH | Alk | Phos | Sili | Y/N |
|---|---|---|---|---|---|
| 10 | 7.99 | | 1.2 | | Y |
| 24 | 8.01 | | 1.3 | | Y |

<<Have minimums been met for this day?

County: Clackamas Agency: C

## ENTRY POINT B

## PWS ID 4100547

## MULINO WATER DISTRICT

**Sample period:** 02-2026
Month/Year

**Number of excursions during this month:** 0

*(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.*

*Reference*

**Minimum Water Quality Parameter(s) as set by State:**

pH 7.3

(No = N = Excursion) **Total N's** 0

Print Name: Dan Frajo

Signature: [signature]

Date: 2-26-26

Send to DWP within 10 days after end of sampling period

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp