Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.7	23.7			Y
2	7.7	26.8			Y
3	7.7	27			Y
4	7.7	29.2			Y
5	7.7	24.8			Y
6	7.6	26.5			Y
7	7.7	26.7			Y
8	7.9	28.3			Y
9	7.9	26.5			Y
10	7.8	26			Y
11	7.7	26.5			Y
12	7.7	28.5			Y
13	8	27.9			Y
14	8	25.8			Y
15	7.9	26.8			Y
16	7.7	24.8			Y
17	7.6	25.3			Y
18	7.6	24.8			Y
19	7.7	23.7			Y
20	7.6	22.8			Y
21	7.7	21.5			Y
22	7.7	22.8			Y
23	7.6	21.4			Y
24	7.5	20.5			Y
25	7.8	21			Y
26	7.8	21.4			Y
27	7.8	22.8			Y
28	7.8	23.2			Y

<< Have minimums been met for this day

(No = N = Excursion) Total N's 0

ENTRY POINT
A
PWS ID 4100591
OREGON CITY - SOUTH FORK W B
Sample Period: February 2025
Month/Year

Number of excursions* during this month: 0

(*Count the number of days when any WQP was less than the minimum required*)

Total excursions during previous 5 months: 0

(*Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative*)

Is system in compliance? Y

Reference
Minimum Water Quality Parameters as set by State:

pH	7.5
Alk	20.0

Print Name: Richard M. Cage
Signature : Richard M Cage
Date: 3/4/25
Phone # 503-657-5030

Send this form to DWP within 10 days after end of sampling period
OHA Drinking Water Program. PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405