Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.7	27.9			Y
2	7.7	27			Y
3	7.7	28.5			Y
4	7.9	29.3			Y
5	7.9	28.1			Y
6	7.8	27.9			Y
7	7.7	28.3			Y
8	7.6	27.6			Y
9	7.7	27.4			Y
10	7.7	32			Y
11	7.8	25.9			Y
12	7.7	26.2			Y
13	7.7	25.9			Y
14	7.8	25.9			Y
15	7.9	24.5			Y
16	7.7	26.2			Y
17	7.8	26.2			Y
18	7.8	28.1			Y
19	7.8	24.7			Y
20	7.8	25			Y
21	7.8	24.4			Y
22	7.7	25.2			Y
23	7.6	26.1			Y
24	7.7	27			Y
25	7.8	22.5			Y
26	7.8	22.9			Y
27	7.8	22.5			Y
28	7.9	23.8			Y
(No = N = Excursion) Total N's				0	

<< Have minimums been met for this day

ENTRY POINT

A

PWS ID 4100591

OREGON CITY - SOUTH FORK W B

Sample Period: Feb-26

Month/Year

Number of excursions* during this month: 0

(*Count the number of days when any WQP was less than the minimum required*)

Total excursions during previous 5 months: 0

(*Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative*)

Is system in compliance? Y

Reference

Minimum Water Quality

Parameters as set by State:

pH	7.5
Alk	20.0

Print Name: Richard M. Cage

Signature : Richard M. Cage

Date: March 5, 2026

Phone # 503-657-5030

Send this form to DWP within 10 days after end of sampling period

OHA Drinking Water Program. PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405