Lead & Copper Rule Corrosion Control

DHS / Oregon department of human services

Day	pH	Alk	Phos	Sili	Y/N
1	7.5				Y
2	7.5				Y
3	7.5				Y
4	7.5				Y
5	7.4				Y
6	7.4				Y
7	7.4				Y
8	7.4				Y
9	7.4				Y
10	7.4				Y
11	7.5				Y
12	7.5				Y
13	7.5	25			Y
14	7.4				Y
15	7.4				Y
16	7.4				Y
17	7.5				Y
18	7.4				Y
19	7.4				Y
20	7.5				Y
21	7.5				Y
22	7.5				Y
23	7.4	23			Y
24	7.4				Y
25	7.4				Y
26	7.5				Y
27	7.4				Y
28	7.5				Y
29	7.5				Y
30	7.6				Y

<<Have minimums been met for this day?

(No = N = Excursion) Total N's: Ø

ENTRY POINT
A
PWS ID 4100926
WALDPORT, CITY OF

Sample period: 09/21
Month/Year

Number of excursions* during this month: Ø
(Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months: Ø
(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)
Is system in compliance? (Y) N

Reference

Minimum Water Quality Parameters as set by State:

pH | 7.2

Print Name: Lyle T Arrant
Signature: Lyle T. Arrant
Date: 10/05/21

Send to OHD within 10 days after end of sampling period

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381