Oregon Health Authority

Water Quality Parameter Monitoring Form

# Lead & Copper Rule Corrosion Control

| | ID # | Sample Location | pH | Alk | PO4 | other | Y/N |
|---|---|---|---|---|---|---|---|
| 3-1 | | | 7.4 | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| 3-8 | | | 7.4 | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| 3-15 | | | 7.5 | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| 3-22 | | | 7.3 | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| 3-29 | | | 7.4 | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

(N = No = Excursion) **Total N's** [ ]

<Has sample met the minimums?

## DISTRIBUTION

**PWS ID: 41** 0 1 1 2 5

**System Name:** MT View CO-OP A

**Sample Period:** MARCH 2024 (Month/Year)

**Sample Frequency:** Weekly

**Distribution Samples required:** ____

**Number of excursions during this Sample Period =** ____

*(Number of locations when any WQP was less than the minimum.)*

*Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.*

*For OHA use only*

**Minimum Water Quality Parameters as set by**

| | | |
|---|---|---|
| pH | 7.1 | |
| Alk | | *(Alkalinity)* |
| PO4 | | *(Orthophosphate)* |
| Other | | (____) |

**Print Name:** Ricky White

**Signature:** Ricky White

**Date:** 4-2-24

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/