Oregon Health Authority

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	ID #	Sample Location	pH	Alk	PO4	other	Y/N
9-5			7.3				
9-12			7.3				
9-19			7.5				
9-26			7.4				

(N = No = Excursion) **Total N's** ____

<Has sample met the minimums?

DISTRIBUTION

PWS ID: 41 01125

System Name: MT View CO-OP A

Sample Period: Sept 2025
Month/Year

Sample Frequency: weekly

Distribution Samples required: ____

Number of excursions during this Sample Period = ____

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

For OHA use only

Minimum Water Quality Parameters as set by

pH	7.1	
Alk		*(Alkalinity)*
PO4		*(Orthophosphate)*
Other		(____________)

Print Name: Ricky White

Signature: [signature]

Date: 9-30-2025

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: http://healthoregon.org/dwp/