Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

DHS oregon department of human services

Day	pH	Alk	Phos	Sili	Y/N
7/1	7.5				
7/2	7.5				
7/3	7.5				
7/8	7.5				
7/10	7.4				
7/11	7.4				
7/15	7.7				
7/16	7.5				
7/17	7.5				
7/18	7.4				
7/19	7.4				
7/22	7.3				
7/23	7.4				
7/24	7.4				
7/25	7.4				
7/29	7.4				
7/30	7.5				
7/31	7.4				

<<Have minimums been met for this day?

(No = N = Excursion) **Total N's** 0

County: Linn Agency: Linn

ENTRY POINT

EP-A

PWS ID 4191707

PLEASANT VALLEY ELEM SD #55

Sample period: July 2024
Month/Year

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference emailed 8-8-24

Minimum Water Quality Parameter(s) as set by State:

pH 7.2

Print Name: Lori Weinman
Signature: Lori M W
Date: 8-8-2024

Send to DWP within 10 days after end of sampling period

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp