Water Quality Parameter Monitoring Form

# Lead & Copper Rule Corrosion Control

DHS oregon department of human services

| Day | pH | Alk | Phos | Sili | Y/N |
|---|---|---|---|---|---|
| 8/1 | 7.5 | | | | |
| 8/4 | 7.5 | | | | |
| 8/5 | 7.5 | | | | |
| 8/6 | 7.4 | | | | |
| 8/7 | 7.4 | | | | |
| 8/8 | 7.4 | | | | |
| 8/11 | 7.5 | | | | |
| 8/12 | 7.5 | | | | |
| 8/13 | 7.5 | | | | |
| 8/14 | 7.6 | | | | |
| 8/15 | 7.5 | | | | |
| 8/18 | 7.5 | | | | |
| 8/19 | 7.5 | | | | |
| 8/20 | 7.5 | | | | |
| 8/21 | 7.5 | | | | |
| 8/22 | 7.5 | | | | |
| 8/25 | 7.5 | | | | |
| 8/26 | 7.5 | | | | |
| 8/27 | 7.5 | | | | |
| 8/28 | 7.4 | | | | |
| 8/29 | 7.5 | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

(No = N = Excursion) **Total N's** 0

<<Have minimums been met for this day?

County: Linn Agency: Linn

## ENTRY POINT

## EP-A

## PWS ID 4191707

**PLEASANT VALLEY ELEM SD #55**

**Sample period:** August 2025
Month/Year

**Number of excursions during this month:** 0

*(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.*

*Reference* emailed 9-3-25

**Minimum Water Quality Parameter(s) as set by State:**

pH 7.2

Print Name: Lori Weinman

Signature: Lori M Weinman

Date: 9-3-2025

Send to DWP within 10 days after end of sampling period

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp