Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

DHS oregon department of human services

Day	pH	Alk	Phos	Sili	Y/N
12/1	7.6				
12/2	7.5				
12/3	7.5				
12/4	7.5				
12/5	7.5				
12/8	7.5				
12/9	7.5				
12/10	7.5				
12/11	7.6				
12/12	7.5				
12/15	7.5				
12/16	7.5				
12/17	7.5				
12/18	7.5				
12/19	7.5				

<<Have minimums been met for this day?

(No = N = Excursion) **Total N's** 0

County: Linn Agency: Linn

ENTRY POINT

EP-A

PWS ID 4191707

PLEASANT VALLEY ELEM SD #55

Sample period: December 2025
Month/Year

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State. Closed over 22nd - 31st

Reference emailed 1-6-26

Minimum Water Quality Parameter(s) as set by State:

pH 7.2

Print Name: Loni Weinman

Signature: Loni Weinman

Date: 1-6-26

Send to DWP within 10 days after end of sampling period

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp