Oregon Health Authority

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	Sample Location	pH	Alk	PO4	Other	Y/N
1						
2		7.6				y
3						
4						
5						
6						
7						
8						
9		7.6				Y
10						
11						
12						
13						
14						
15						
16		7.5				Y
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30		7.5				Y
31						
(N = No = Excursion)		**Total N's**				Ø

< Has sample met the minimums?

DISTRIBUTION

PWS ID: 41 | 9 | 1 | 8 | 0 | 5 |

System Name: Elmira High / Elementary

Sample Period: Dec. 2025
Month/Year

Sample Frequency: Weekly

Distribution Samples required: _____

Number of excursions during this Sample Period = Ø

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

--- For OHA use only ---

Minimum Water Quality Parameters as set by

pH	7.2	
Alk		*(Alkalinity)*
PO4		*(Orthophosphate)*
Other		*(_____)*

Print Name: Daniel Pinteman

Signature: _____

Date: 1. 6. 25

Send to Drinking Water Program within 10 days after end of sampling period