Oregon Health Authority

Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

ID #	Sample Location	pH	Temp	Chlor	Other	Y/N
9/4	Work Rm	8.0	55	.5	/	Y
9/6	"	7.9	55	.4	/	Y
9/12	"	7.9	55	.4	/	Y
9/14	"	7.6	56	.3	/	Y
9/18	"	7.6	55.5	.4	/	Y
9/20	"	7.6	55.1	.5	/	Y
9/26	"	7.8	55.5	.6	/	Y
9/28	"	7.7	55.4	.4	/	Y
		7.7	55.5	.4	/	Y
		7.7	55.6	.4	/	Y

(N = No = Excursion) **Total N's** Ø

<Has sample met the minimum(s)?

County: Lincoln Agency: LINCOLN C

DISTRIBUTION

PWS ID 4192040

EDDYVILLE CHARTER SCHOOL

Sample Period: Sept 23
Month/Year

Sample Frequency: Every 6 months

Distribution Samples required: 1

Number of excursions during this Sample Period = Ø

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

Reference

Minimum Water Quality Parameters as set by State:

pH 7.2

Print Name: Danny W.
Signature: [signature]
Date: 10/4/23

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: http://healthoregon.org/dwp/