Oregon Health Authority

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID #	Sample Location	pH	TEMP	Chlor	Other	Y/N
2/1	Work Room	7.8	50	.4	/	Y
2/5	" "	7.7	50	.3	/	Y
2/7	" "	7.8	49	.4	/	Y
2/9	" "	7.9	50	.4	/	Y
2/13	" "	7.9	51	.5	/	Y
2/15	" "	7.8	50	.4	/	Y
2/19	" "	7.8	50	.4	/	Y
2/21	" "	7.8	49	.3	/	Y
2/23	" "	7.8	49	.3	/	Y
2/27	" "	7.7	49	.4	/	Y
2/29	" "	7.7	49	.3	/	Y

(N = No = Excursion) **Total N's** Ø

<Has sample met the minimum(s)?

County: Lincoln Agency: LINCOLN C

DISTRIBUTION

PWS ID 4192040

EDDYVILLE CHARTER SCHOOL

Sample Period: Feb / 24
Month/Year

Sample Frequency: Every 6 months

Distribution Samples required: 1

Number of excursions during this Sample Period = 0

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

Reference

Minimum Water Quality Parameters as set by State:

pH 7.2

Print Name: Danny Shuler

Signature:

Date: 3/5/24

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: http://healthoregon.org/dwp/