

CROSS CONNECTION BOARD POLICY



DRINKING WATER COLUMNS

FRIST ADDITION TO MOYINA IMPROVEMENT DISTRCIT

PWS 4100434

UPDATED 2-25-99

First Addition to Moyina Improvement District serves less than 300 service connections. Two cross connection inspections are completed yearly. Back flow prevention devices are properly installed and are inspected yearly by a certified inspector.

Our local ordinance, as hereby approved by the Board of First Addition to Moynia Improvement District, prohibits water service to any premise on which a cross connection exists without proper protection and will result in discontinuing water service to said premise.

Inspections are completed by the City of Klamath Falls, Water Department, Randal Travis Cross Connection Control, Steven D. Blum Inspector # 1130.