



800 NE Oregon Street, Suite #640
Portland, OR 97232-2162
(971) 673-0405
(971) 673-0694 – FAX
<http://healthoregon.org/dwp>

February 29, 2024

Cody Nelson
Golf MHP, LLC
5445 32nd Avenue SW
Seattle, WA 98126

RE: Nitrate maximum contaminant level exceeded at the Golf Mobile Home Park public water system. ID# OR4100588

Dear Cody Nelson,

A recent sample reported for your water system indicates nitrate in the drinking water exceeds the maximum contaminant level (MCL) of 10 mg/L. This demonstrates your water system's existing treatment is not effectively reducing the concentration of nitrate to below the MCL. Nitrate is a drinking water contaminant and infants below the age of 6 months who drink water containing nitrate in excess of the MCL could become seriously ill and, if untreated, may die. Symptoms include shortness of breath and blue baby syndrome. OAR 333-061-0097

Please consult with Bill Goss at 541-966-0900 immediately so that you can abate the contamination as quickly as possible.

You must also:

- 1) Submit a written report to the Oregon Health Authority, Drinking Water Services (DWS) no later than 30 days after the date of this letter identifying the reason for treatment failure at your water system. This report must include how you plan to restore treatment to effective operation and be submitted to bradley.k.daniels@oha.oregon.gov.
- 2) Restore treatment to effective operation and report sample results demonstrating the concentration of nitrate in drinking water is below the MCL no later than 30 days after the date of this letter. If circumstances beyond your control prevent you from restoring treatment to effective operation within 30 days, you must explain in writing the reasons you are unable to restore treatment and include a corrective action plan indicating how you will abate the contamination and reduce concentrations of nitrate in drinking water to below the MCL, as quickly as possible.

- 3) Issue public notice to customers within 24 hours if not completed previously and submit a copy to DWS at compliance.dw@odhsoha.oregon.gov within 10 days of the date of this letter. An appropriate public notice template is available online at <https://www.oregon.gov/public-notices>. Please complete the template with information for your water system and distribute the notice to customers as soon as possible. This notice must be re-issued every three months until the contamination has been resolved.


If water system alterations are necessary to resolve the contamination, construction plans must be approved according to OAR 333-061-0060 prior to construction of new treatment facilities or modifications to existing water system facilities.

You can contact DWS circuit rider for technical assistance at mgochnour@civilwest.net or 541-266-8601. Visit the webpage: <https://www.oregon.gov/oha/PH/HEALTHYENVIRONMENTS/DRINKINGWATER/OPERATIONS/Pages/circuitrider.aspx> for more information about the DWS circuit rider program.

The actions described in this letter are required by Oregon Administrative Rules 333-061-0025, 333-061-0030 and 333-061-0042. Please contact me at bradley.k.daniels@oha.oregon.gov or (503) 735-5438 if you have any questions or to discuss the actions required in this letter.

Thank you for your immediate attention to this matter.

Respectfully,



Brad K. Daniels

Compliance Specialist

Oregon Health Authority, Drinking Water Services

cc: Bill Goss, Oregon Health Authority, Drinking Water Services
Amy Word, Oregon Health Authority, Drinking Water Services