

2/12/2025

CRAIG MONSON
CLINE FALLS OASIS IMPRV DIST
8202 NW OASIS DRIVE
REDMOND, OR 97756

RE:Installation of treatment to maintain a disinfectant residual due to persistent coliform bacteria at OR4100694

Dear CRAIG MONSON,

Due to recent coliform sample results, the Oregon Health Authority, Drinking Water Services (DWS) is requiring another coliform investigation. The number of coliform investigations at your water system without removing the source of the coliform bacteria requires the installation of treatment to maintain a disinfectant residual throughout the distribution system according to Oregon Administrative Rule 333-061-0032(6)(g).

Treatment must be installed no later than 8/15/2025. Plan review is required prior to installation. Please review the requirements at www.healthoregon.org/pwsplanreview.

If you have any questions please contact Jeff Freund at (541) 388-6563.

Respectfully,

Drinking Water Services

cc: Josh Seerup, DWS

Jeff Freund, Deschutes County