

7/25/2025

JON ESTES

BAILEY NURSERY REEDER RD MAIN  
14301 SE WALLACE RD  
DAYTON, OR 97114

RE:Installation of treatment to maintain a disinfectant residual due to persistent coliform bacteria at OR4195481

Dear JON ESTES,

Due to recent coliform sample results, the Oregon Health Authority, Drinking Water Services (DWS) is requiring another coliform investigation. The number of coliform investigations at your water system without removing the source of the coliform bacteria requires the installation of treatment to maintain a disinfectant residual throughout the distribution system according to Oregon Administrative Rule 333-061-0032(6)(g).

Treatment must be installed no later than 1/27/2026. Plan review is required prior to installation. Please review the requirements at [www.healthoregon.org/pwsplanreview](http://www.healthoregon.org/pwsplanreview).

If you have any questions please contact Jenifer George/Jeff Martin/Shannon Foster/Rhonda Robb at (971) 219-2523.

Respectfully,

Drinking Water Services

cc: Carrie Gentry, DWS

Jenifer George/Jeff Martin/Shannon Foster/Rhonda Robb, Multnomah County