

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.0	25			
2	7.0	38			
3	7.2	43			
4	7/2	34			
5	7.2	35 38 43 34 33			
6	711	42			
7		38			
8	7.1	41			
9	7.0	41 34 35			
10	7,0	35			
11	7.1	40			
12	7.0	42			
13	7,8	43			
14	7,1 7.0 7.0 7.0 7.0 7.0 7.0 7.0 7.0	40 42 43 39 40 43 38			
15	7.0	40			
16	7,0	43			
17	7.1	38			
18	7.0	36 32 36 36			
19	7.0	32			
20	7.0	36			
21	7,0	36			
22	7,0	35			
23	7,0	37			
24	7,0	42			
25	7.2	36			
26	711	41			
27	7.0	37			
28	7.0	35			
29	7.1	36			
30	7.3	38			
31					
1o = 1	\ = Exc	cursion)Tota	l N's	Ö

< <have minimums</have 	County: Hood River Agency: HOOD RIVER COUNTY ENTRY POINT				
been met for this day?	EP-A				
PWS ID 4100172 CASCADE LOCKS, CITY OF					
Sample period: 5 < p + 2024 Month/Year					

Number of excursions during this month: _______

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference ——————				
Minimum Water Quality Parameter(s) as set by State:				
pH 7.0 Alk 31.0 (Alkalinity)				
Drint Names Charlet a contract				

Signature: Shellon Price

Signature: Shellon Price

Date & Phone#: 9-30-24/54/490 56/0

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/