

)(
 DHS
 Oregon Department
 of Human Services

Water Quality Parameter Monitoring Form
 Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.4	N/A	N/A	N/A	YES
2	7.4	N/A	N/A	N/A	YES
3	7.4	N/A	N/A	N/A	YES
4	7.5	N/A	N/A	N/A	YES
5	7.5	N/A	N/A	N/A	YES
6	7.4	N/A	N/A	N/A	YES
7	7.4	N/A	N/A	N/A	YES
8	7.4	N/A	N/A	N/A	YES
9	7.4	N/A	N/A	N/A	YES
10	7.4	N/A	N/A	N/A	YES
11	7.5	N/A	N/A	N/A	YES
12	7.4	N/A	N/A	N/A	YES
13	7.4	N/A	N/A	N/A	YES
14	7.4	N/A	N/A	N/A	YES
15	7.4	N/A	N/A	N/A	YES
16	7.4	N/A	N/A	N/A	YES
17	7.4	N/A	N/A	N/A	YES
18	7.5	N/A	N/A	N/A	YES
19	7.4	N/A	N/A	N/A	YES
20	7.4	N/A	N/A	N/A	YES
21	7.4	N/A	N/A	N/A	YES
22	7.4	N/A	N/A	N/A	YES
23	7.4	N/A	N/A	N/A	YES
24	7.4	N/A	N/A	N/A	YES
25	7.4	N/A	N/A	N/A	YES
26	7.6	N/A	N/A	N/A	YES
27	7.4	N/A	N/A	N/A	YES
28	7.4	N/A	N/A	N/A	YES
29	7.4	N/A	N/A	N/A	YES
30	7.4	N/A	N/A	N/A	YES
31	7.3	N/A	N/A	N/A	YES

(No=N=Excursion)

Total N's

<<Have County: Lane Agency: REGION 2
 minimums ENTRY POINT
 been met for Entry Point: EP-B
 this day? PWS ID 4100246B
 System Name: Creswell, City of
 Sample pe 44197
 Month/year

Number of excursions during this month: 0
 (Over 9 excursions in 6 months is a violation.
 Entry Point and Distribution excursions are
 cumulative). An 'excursion' is any day in which the
 water quality parameter(s) fall below the minimum
 set by the State.

Reference: Minimum pH set on 11/3/2003 By John Potts.

Minimum Water Quality
 Parameter(s) as set by State:

pH 7.1
 Alk N/A (Alkalinity)
 PO4 N/A (Orthophosphate)
 Sili N/A (Silicate)

Print Name Mike Howard

Signature: Mike Howard
 541-736-6015
 44231

Send to DWP within 10 days after end of sampling period
 DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
 Phone:(971) 673-0405 Website: <http://oregon.gov/DHS/ph/dwp/index.shtml>