



DHS

Oregon Department of Human Services

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N	<<Have minimums been met for this day?	County: Lane Agency: REGION 2
1	7.7	38	N/A	N/A	YES		<b>ENTRY POINT</b> Entry Point: EP-B PWS ID 4100246B
2	7.7	40	N/A	N/A	YES		
3	7.7	40	N/A	N/A	YES		System Name: <u>Creswell, City of</u>
4	7.6	40	N/A	N/A	YES		
5	7.6	40	N/A	N/A	YES		Sample period: <u>May-24</u> Month/year
6	7.6	40	N/A	N/A	YES		
7	7.6	38	N/A	N/A	YES		<b>Number of excursions during this month: <u>0</u></b> <i>(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.</i>
8	7.5	36	N/A	N/A	YES		
9	7.5	38	N/A	N/A	YES		
10	7.5	38	N/A	N/A	YES		
11	7.4	40	N/A	N/A	YES		
12	7.4	40	N/A	N/A	YES		
13	7.4	40	N/A	N/A	YES		
14	7.5	44	N/A	N/A	YES		
15	7.5	42	N/A	N/A	YES		
16	7.5	42	N/A	N/A	YES		
17	7.5	42	N/A	N/A	YES		Reference: Minimum pH set on 11/3/2003 By John Potts.
18	7.4	40	N/A	N/A	YES		
19	7.4	40	N/A	N/A	YES		
20	7.4	40	N/A	N/A	YES		
21	7.5	41	N/A	N/A	YES		
22	7.6	43	N/A	N/A	YES		
23	7.5	42	N/A	N/A	YES		
24	7.5	42	N/A	N/A	YES		
25	7.4	40	N/A	N/A	YES		
26	7.4	40	N/A	N/A	YES		
27	7.4	40	N/A	N/A	YES		<b>Print Name: Mike Howard</b>
28	7.4	36	N/A	N/A	YES		
29	7.5	38	N/A	N/A	YES		
30	7.5	40	N/A	N/A	YES		
31	7.5	40	N/A	N/A	YES		<b>Signature: Mike Howard</b> <b>541-736-6015</b> <b>6/1/2024</b>
(No=N=Excursion)						<b>Total N's</b>	