'(	DHS							
C	Oregon Department					Water Quality Parameter Monitoring Form		
	of Human Services	Human Services Lead				& Copper Rule Corrosion Control		
Day	рН	Alk	Phos	Sili	Y/N	< <have< td=""><td>County: Lane Agency: REGION 2</td></have<>	County: Lane Agency: REGION 2	
1	7.4	38	N/A	N/A	YES	minimums	ENTRY POINT	
2	7.4	36	N/A	N/A	YES	been met for	Entry Point: EP-B	
3	7.5	38	N/A	N/A	YES	this day?	PWS ID 4100246B	
4	7.5	38	N/A	N/A	YES		System Name: Creswell, City of	
5	7.5	40	N/A	N/A	YES		Sample period: October-24	
6	7.5	40	N/A	N/A	YES		Month/year	
7	7.5	40	N/A	N/A	YES			
8	7.5	38	N/A	N/A	YES		Number of excursions during this month: <u>0</u>	
9	7.5	38	N/A	N/A	YES		(Over 9 excursions in 6 months is a violation.	
10	7.5	40	N/A	N/A	YES		Entry Point and Distribution excursions are	
11	7.5	40	N/A	N/A	YES		cumulative). An 'excursion' is any day in which the	
12	7.5	40	N/A	N/A	YES		water quality parameter(s) fall below the minimun	
13	7.5	40	N/A	N/A	YES		set by the State.	
14	7.5	40	N/A	N/A	YES			
15	7.4	42	N/A	N/A	YES			
16	7.4	42	N/A	N/A	YES			
17	7.3	44	N/A	N/A	YES		Reference: Minimun pH set on 11/3/2003 By John Potts.	
18	7.4	42	N/A	N/A	YES			
19	7.5	42	N/A	N/A	YES		Minimum Water Quality	
20	7.5	42	N/A	N/A	YES		Parameter(s) as set by State:	
21	7.5	40	N/A	N/A	YES			
22	7.4	40	N/A	N/A	YES		pH 7.1	
23	7.4	40	N/A	N/A	YES YES		Alk 33 (Alkalinity) PO4 N/A (Orthophosphate)	
24	7.4	40	N/A	N/A				
25	7.4	40	N/A	N/A	YES YES		Sili N/A (Silicate)	
26 27	7.4	40	N/A	N/A	YES		Print Name: Mike Howard	
27	7.5	42	N/A	N/A	_		FIIIL NAME. MIKE HOWAIU	
28	7.5	42	N/A	N/A	YES			
29	7.5	40	N/A	N/A	YES		Signature: Mike Howard	
30	7.5	40	N/A	N/A	YES		541-736-6015	
31	7.5	40	N/A	N/A	YES		11/1/2024	
lo=N=Excursion	ו)	Total N's				Send to DWP within 10 days after end of sampling period		
					DHS, Drin	king Water Progra	m, PO Box 14350, Portland, OR 97293-0350	