)'(	DHS Oregon Departmen of Human Services	t			Lead & C	•	rameter Monitoring Form		
Day 1	рН 7.8	Alk 41	Phos N/A	Sili N/A	Y/N YES	< <have minimums</have 	County: Lane Agency: F	REGION 2 ENTRY POINT	
2	7.6	38	N/A	N/A	YES	been met for		Entry Point: EP-B	
3	7.6	40	N/A	N/A	YES	this day?		PWS ID 4100246B	
4	7.6	40	N/A	N/A	YES	ano day :	System Name: Creswell, C		
5	7.7	40	N/A	N/A	YES	-	Sample period:	January-25	
6	7.7	40	N/A	N/A	YES	-	Sample period.	Month/year	
7	7.6	38	N/A N/A	N/A N/A	YES	-		wontri/year	
8	7.6	38	N/A	N/A	YES	-	Number of excursions du	ring this month: 0	
9	7.5	38	N/A	N/A	YES	-	(Over 9 excursions in 6 mo	-	
10	7.5	40	N/A	N/A	YES	-	Entry Point and Distribution		
11	7.5	40	N/A	N/A	YES	-	cumulative). An 'excursion'		
12	7.5	40	N/A	N/A	YES		water quality parameter(s) f		
13	7.6	38	N/A	N/A	YES		set by the State.		
14	7.6	36	N/A	N/A	YES				
15	7.7	38	N/A	N/A	YES				
16	7.6	38	N/A	N/A	YES	_			
17	7.6	38	N/A	N/A	YES	_			
18	7.6	40	N/A	N/A	YES	_			
19	7.6	40	N/A	N/A	YES		Minimum Water Quality		
20	7.6	40	N/A	N/A	YES		Parameter(s) as set by St	ate:	
21	7.4	38	N/A	N/A	YES			-	
22	7.4	38	N/A	N/A	YES	_	рН 7.1		
23	7.4	38	N/A	N/A	YES	_	Alk 33	(Alkalinity)	
24	7.6	38	N/A	N/A	YES	-	PO4 N/A	(Orthophosphate)	
25 26	7.6	40 40	N/A	N/A	YES YES	-1	Sili N/A	(Silicate)	
26	7.6	40	N/A N/A	N/A N/A	YES	-	Print Name:	Mike Howard	
-						-		WING HOWAIG	
28	7.5	40	N/A	N/A	YES	-	Signature: Mike Hov	word	
29	7.6	38	N/A	N/A	YES	4	Signature: wike Hov		
30	7.6	40	N/A	N/A	YES	4		541-736-601	
31	7.6	40	N/A	N/A	YES	2/1/2025			
(No=N=Excursion) Total N's						Send to DWP within 10 days after end of sampling period			
					DHS, Drinking Phone:(971)		O Box 14350, Portland, OR 972 Website: http://oregon.gov/		