

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

ID#	Sample Location	pH	AIR	PQ4	other	YIN	<has sample<="" th=""></has>
(4)	# 61	7,22				4	met the DISTRIBUTIO
310		71.25				4	
PA		1.29				J	PWS ID: 41 0 0 Z 9 5
Ą	11	11.1				V	System Name: Big Struce MHP
20	n.	724			V. 13	V	Sample Period: May 2024
24"	ď	H23				4	Sample Frequency: Month/Year
297	<b>81</b>	725				V	Distribution Samples required:
		(37)					
					30.5		Number of excursions during this
							Sample Period =
							(Number of locations when any WQ
							was less than the minimum.)
							Note: Entry Point and Distribution
							Excursions are cumulative. Add Enti
							Point and Distribution Excursions to total for sample period.
							For OHA use only
							Minimum Water Quality Parameters as set by
							pH 7.1
					1	4: 1	Alk (Alkalinity)
							PO4 (Orthophosphat
							Other /
7.79	但是是是此的数据,	1					Print Name: asheu mair

Send to Cirinking Water Program within 10 days after end of sampling period: CHA Drinking Water Program, PO Box 14350; Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/