

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	< <have *="" entry="" point<="" th=""></have>
1	723				Y	HIIIIIIIIII
2						been met for this day? PWS ID: 41 0:03 11
3						tills day:
4						System Name: City of Garibaldi Entry Point: first Hydrant Refore Sarvices
5						
6						Sample Period: June
7						Month/Year
8			ļ			Number of excursions* during this month:
9						(Count the number of days when any WQP was
10						less than the minimum required)
11	7.10				Y	
12						Total excursions during the previous 5 months:
13	1.0		-	ļ		(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)
14	7.12				Y	Point and Distribution excursions are cumulative )
15			-	ļ		For OHA use only
16			-	ļ		
17			<del> </del>	-		Minimum Water Quality
18			-	-		Parameters as set by
19 20			<del> </del>	<u> </u>		pH 7.1
21			<del> </del>	<del> </del>		Alk (Alkalinity)
22			-	-		PO4 (Orthophosphate)
23						Other ()
24	-		+		-	
25			-	-		
26			+			
27				2 2		V 11 2 2
28	7.29		1		V	Print Name: Kelly West
29	1.01				+	Signature:
30						Date: 7-2-21
31						Send to DWP within 10 days after end of
No = N = Excursion) Total N's					0	sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/