

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	Day	pH	Alk	Phos	Sili	Y/N
	1	7.41				Ų
	2	7.46				1
	3	7.49				
-	4	7.33			X	
	5	7.40				
	6	7.42				
	7	7.45				
-	8	7.43				
	9	7.31				
	10	7.66				
L	11	7.59				1
L	12	7.66				T
L	13	7.52				
L	M	7.44				1
	15	7,46				1
	16	7-42				
-	17	7.26				TI
	18	7.25				1
-	19	7.29				
0	20	7.25				
-	11	7,31				
	12	7.24				
2	13	7.26				
2	4	7.26				
	5	7.31				
20	-	7.36				
2		7.36				
	8	7.36				
2	9	7.41				
3	0	7.37				
3	1 -	1.52			C	7

<<Have minimums been met for this day?

County: Tillamoak

ENTRY POINT

PWS ID 4100367

HEBO JOINT WATER & SANITARY AUTH.

Number of excursions* during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

Reference

Minimum Water Quality Parameters as set by State:

7.2

Date:09/0

Print Name: Signature:

Send to OHD within 10 days after end of sampling period

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381