

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.69	69			4
2	7.68				
3	7.70	71			
4	7.72				
5	7.70	69			
6	7.71				
7	7.68	69	E		
8	7.64				
9	7.66	te7			
10	7.68				
11	7.69	68			
12	7.72				
13	7.70	70			
14	7.68				
15	7-66	67			
16	7.66		STREET		
17	7.64	Cele			
18	7.70				
19	7.63	65			
20	7-60				
21	7.63	660			
22	7.68				
23	7.64	65			
24	7. lelo				
25	7.69	68			
26	סרור				
27	7.69	70			
28	7.71				
29	7.66	68			
30	764				
31	7.68	67			4
(No = N	l = Exc	ursion	Tota	N's	0

<<Have minimums been met for this day?

County: Tillamook Agency: TILLAMOOK COUNTY

ENTRY POINT

EP-A

PWS ID 4100367

HEBO JOINT WATER & SANITARY AUTH

Sample period: Januar

Month/Year

Number of excursions during this month: _________

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the

State.

		ater Quality) as set by State
рН	7.2	(Alkalinity)
Alk	60.0	(Alkalinity)

Print Name: Justin Hartford
Signature: Oth Hartford

Date & Phone#: 02/09/2025 503-392-6100

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/