

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.67	70			Q
2	7.69				1
3	7.66	73			
4	7.60				
5	7.63				
6	7.64	74			
7	7.70				
8	7.68			)	
9	7.71	76			
10	7.69				
11	7.67				
12	7.70	74			
13	コウン				
14	7.19	72			
15	7.66				
16	7.68				
17	7.71	75			
18	7.76				
19	7,73				
20	7.70	71			
21	7.66				
22	7.64				
23	7.60	72			
24	7.58				
25	7.56				
26	7.62	69			
27	7.65				1
28	7.69	71			4
29					
30					
31					
lo = N = Excursion) <b>Total N's</b>					(1)

County: Tillamook Agency: TILLAMOOK COUNTY

ENTRY POINT

EP-A

PWS ID 4100367

HEBO JOINT WATER & SANITARY AUTH

Sample period: February 2025

Month/Year

Number of excursions during this month: Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).

An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality
Parameter(s) as set by State:

pH 7.2
Alk 60.0 (Alkalinity)

Print Name: 103 1 2025 503-312-600

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/