

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Da	у р	Н	Alk	P	hos	Othe	r	<b>//N</b>
1	7.	20	74					4
2	7.	69					1	1
3	7.6	pil					1	
4	7.4	20	70				T	
5	7.5	8						
6	7,5	6						
7	7.5	9						
8	7.5	u	68					
9	7.5							
10	7.5	2						
11	7.5							
12	7.4		69					
13	7.48	_						
14	7.5	_						
15	7.57	_						
16	7.50	_						
17	7.50	_						
18	7-60		71					
19	7.6	_						
20	7.50	_					1	
21	7.55	_					4	
22	7.58		C		-		1	
23	7.61		99				1	
25	7.59						-	
26	7.40		08		+		+	
27	7.52	_	00		+		1	
28	7.36	_			+		+	
29	7,20						-	
30	7.25	_					+	
31	7.36						1	
	7.40	_	rois = \	_			7	4
No = N	v - ⊏>	kcul	sion)	10	tal	N'S	CI	)

<<Have minimums been met for this day?

County: Tillamook Agency: TILLAMOOK COUNTY

**ENTRY POINT** 

EP-A

PWS ID 4100367

**HEBO JOINT WATER & SANITARY AUTH** 

Sample period: MACC

Month Wasi

Month/Year

Number of excursions during this month:



(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Paran	num Wa neter(s	ater Quality ) as set by State:
pH Alk	7.2	(Alkalinity)
Alk	60.0	](Alkalinity)

Print Name: Justin Harthord

Signature:

Date & Phone#: 04/09/2025, 503-392-4100

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/