

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.58	70	= 82-		Y
3	7-60				1
3	7.65				
4	7.74		H	19	
5	7.78				
6	7.86				
7	7.80		C.14		
8	7.79				
9	7.80	72			
10	8.08				
11	8.01				
12	7.98				
13	7.89				
14	7.70				
15	7.68	3 E TO(2			
16	7.21	69			
17	7.20				
18	7.20				
19	7.20				
20	7.25				
21	7.30				
22	7.32				
23	7.30	73			
24	7.36				
25	7.39			-Wos-e	
26	7.31				
27	7.20				
28	7.22				
29	7.30				1
30	7.31	70			Y
31					
lo = N	= Exc	ursion)	Total	N's	0

< <have minimums<="" th=""><th>County: Tillamook Agency: TILLAMOOK COUNTY</th></have>	County: Tillamook Agency: TILLAMOOK COUNTY			
been met for	ENTRY POINT			
this day?	EP-A			
	PWS ID 4100367			
НЕВО ЈО	INT WATER & SANITARY AUTH			
Sample pe	riod: April 2025			

Number of excursions during this month:

Month/Year

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2
Alk 60.0 (Alkalinity)
Print Name: Justin Hartbord
Signature: Little Hitch
Date & Phone#: 05/09/2025 503-392-6100
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/