

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.45	74			4
1 2 3 4	7.47				1
3	7.41				
4	7.41			Water and the same	
5	7,28				
6	7.20				
7	7,21	77			
8	7.25		80000		
9	7.24		440.00		
10	7.22				
11	7.21				
12	7.24				
13	7.24				
14	7.28				
15	7.35	70			
16	7.45				
17	7.45				
18	7.49				
19	7.58				
20	7.62				
21	7.63				
22	7.65	78			
23	7.68				
24	7,70				
25	7.79				
26	7.65		March 1		
27	7.69				
28	7.68				
29	טרור	77			
30	7.66				4
31	Sk p				
10 = V	1 = Exc	ursion	Total	N's	0

<<Have minimums been met for this day?

County: Tillamook Agency: TILLAMOOK COUNTY **ENTRY POINT** EP-A

PWS ID 4100367

HEBO JOINT WATER & SANITARY AUTH

Sample period: _

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

		ater Quality) as set by State:
рН	7.2]
Alk	60.0	(Alkalinity)

Print Name: JUSTIA

Signature:

Date & Phone#: 07/09/2025

503-392-6100

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/