

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.8	78			Y
2	7.8				1-
З	7.71				
4	7.75				
5	7.70				
6	1.73	75			
7	7.67				
8	7.58			3	
9	7.60				
10	اعا، (*				
11	7.59				
12	7.54				
13	7,49				
14	7.61	71			
15	7.74				
16	7,80				
17	7.79				
18	7.80				
19	7.77				
20	8.27				
21	8.57	30			
22	8.31				
23	8.37		7		
24	8.20				
25	8.15				
26	7,95				
27	7.74				
28	7.69				
29	7.87	77			
30	7.53				١
31	7.55				Y
10 = N	N = Exc	ursion	) Tota	l N's	0

<<Have minimums been met for this day?

County: Tillamook Agency: TILLAMOOK COUNTY **ENTRY POINT** 

EP-A

PWS ID 4100367

**HEBO JOINT WATER & SANITARY AUTH** 

Sample period: |

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

			ater Quality ) as set by State
pH 7.2	pH	7.2	(Alkalinity)
Alk 60.0 (Alkalinity)	Alk	60.0	

Print Name: Justin

Signature:/

Date & Phone#: 09/10/2025 503-392-6160

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/