

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

O# Sample Location	рН	Alk	PO4	Other	Y/N
30720 Huy 1015	7.90	70			Y
31055 Huy 1015	7.91	71			7
31255 Huy 1015	7.84	71			Y
30960 Huy 1015	7.80	72			Y
31330 Hwy 1015	7.79	70			4
31020 Hwy 1015	7.82	70			4
30890 Hwy 1015	7.88	69			Y
31003 Hwy 1015	7.96	71			Y
31155 Huy 1015 31145 Huy 22	7.94	72			4
31145 Hwy 22	8.01	73			Y
(N = No = Excu	ursion	) <b>T</b>	otal I	√s ľ	0

<Has sample
met the
minimum(s)?</pre>

County: Tillamook Agency: TILLAMOOK

## DISTRIBUTION

PWS ID 4100367
HEBO JOINT WATER & SANITARY
AUTH

Sample Period: April 2025

Month/Year

Sample Frequency: Every 36 months Distribution Samples required: 1

Number of excursions during this Sample Period = \_\_\_\_\_\_

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

Reference

Minimum Water Quality Parameters as set by State:

pH 7.2 Alk 60.0 (Alkalinity)

Print Name:

Signature:

Date: 04/1/2029

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/