



Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.69				Y
2	7.65				
3	7.70				
4	7.52				
5	7.68				
6	7.60				
7	7.62				
8	7.58				
9	7.69				
10	7.56				
11	7.77				
12	7.52				
13	7.76				
14	7.67				
15	7.60				
16	7.73				
17	7.64				
18	7.70				
19	7.37				
20	7.70				
21	7.82				
22	7.54				
23	7.54				
24	7.60				
25	7.63				
26	7.64				
27	7.56				
28	7.61				Y
29					
30					
31					

<<Have minimums been met for this day?

County Title: _____ Agency: _____

ENTRY POINT

A

PWS ID 4100367

HEBO JOINT WATER & SANITARY AUTH.

Sample period: FEB 2021
 Month/Year

Number of excursions* during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

Reference

Minimum Water Quality Parameters as set by State:

pH 7.2

(No = N = Excursion) Total N's 0

Print Name: Loony E. Moeller
 Signature: Loony E. Moeller
 Date: 3/8/21

Send to OHD within 10 days after end of sampling period

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381