



# Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.55				Y
2	7.48				
3	7.44				
4	7.43				
5	7.46				
6	7.46				
7	7.44				
8	7.41				
9	7.40				
10	7.43				
11	7.45				
12	7.38				
13	7.38				
14	7.34				
15	7.36				
16	7.34				
17	7.25				
18	7.32				
19	7.37				
20	7.39				
21	7.39				
22	7.38				
23	7.33				
24	7.51				
25	7.31				
26	7.27				
27	7.36				
28	7.33				
29	7.29				
30	7.38				Y
31					

<<Have minimums been met for this day?

County Titname: Agency: C

**ENTRY POINT**

**A**

**PWS ID 4100367**

**HEBO JOINT WATER & SANITARY AUTH.**

Sample period: SEPT / 2021  
Month/Year

Number of excursions\* during this month: SEPT  
(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

Reference

Minimum Water Quality Parameters as set by State:

pH 7.2

Print Name: Lenny E. Moeller

Signature: [Handwritten Signature]

Date: 9/30/21

(No - N = Excursion) Total N's 0

Send to OHD within 10 days after end of sampling period  
Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381