Water Quality Parameter Monitoring Form Oregon Health Authority Lead & Copper Rule Corrosion Control

Day	PH	Alk	Phos	Other	Y/N
1	7.8				Υ
2	PLAN	T OFF			
3	7.8				Υ
4	7.8				Υ
5	7.8				Υ
6	7.7				Υ
7	7.9				Υ
8	7.7				Υ
9	7.6				Υ
10	7.7				Υ
11	7.6				Υ
12	7.6				Υ
13	7.7				Υ
14	7.6				Υ
15	7.9				Υ
16	PLANT OFF				
17	7.7				Υ
18	7.7				Υ
19	7.8				Υ
20	7.8				Υ
21	7.7				Υ
22	7.7				Υ
23	PLANT OFF				
24	7.7				Υ
25	7.6				Υ
26	7.6				Υ
27	7.7				Υ
28	7.8				Υ
29	7.8				Υ
30		TOFF			
31	7.7				Υ
Total N's					0

(No = N = Excursion)

< <have< th=""><th>ENTRY POINT</th></have<>	ENTRY POINT
minimums been	
met for this day?	ID: <u>41-00473</u>
System Name:	Lebanon
Entry Point:	WTP-B
Sample Period:	<u>Mar-25</u>
	Month/Year

Number of excursions during this month 0
(Count the number of days when any WQP was less than the minimum required)

Number of excursions during this month 0
(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

For OHA use only

	Minimu	m Wate	er Quality		
Parameter(s) as set by State:					
	MIN	MAX			
Ηq	7.0	9.0			
pH Alk			(Alkalinity)		
PO4			(Orthpphosphate)		
Other			()		

Print Name:

Tyson heen

Signature:

Date:

A-3-25

Sent to DWP within 10 days after end of sampling period.

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (971)-673-0471 Website: www.dhs.state.or.us/publichealth/dwp/index.cfm