

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.6				Y
2	7.5				Y
3	7.5				Y
4	7.5				Y
5	7.5				Y
6	7.6				γ
7	7.7				Y
8	7.7				Υ
9	7.6				Υ
10	7.6				γ
11	7.6				Y
12	7.6				Y
13	7.6				Y
14	7.6				Y
15	7.6				Y
16	7.6				γ
17	7.6				Y
18	7.6				Υ
19	7.6 7.6				γ
20	7.6				Y
21	7.6				Y
22	7.6				Y
23	7.6				Y
24	7.6				7
25	7.6 7.6				Y
26	7.6				Y
27	7.6				Υ
28	7.7				Y
29	7.6				Y
30	7.6				Y
31					

<<Have minimums been met for this day?

County: Linn Agency: LINN COUNTY

ENTRY POINT

EP-A

PWS ID 4100474
LAWRENCE SUBDIVISION WTR ASSN

Sample period: <u>Sept.</u> /2023

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

		er Quality as set by	
рН [	7.2		

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/