

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.5				Y
2	7.5 7.5 7.5				Y
3	7.5				V
4	7.5				V
5	7.6				Y
6	76				y
7	7.6				Y
8	7.6				Y
9	7.6				Y
10	7.6				Ÿ
11	7.5				Y
12	7.5				Y
13	7.5				Y
14	7.5				Y
15	7.5				Y
16	7.5				Y
17	7.4				Y
18 19	7.4				Y
19	7.4				Y
20	7.4				Y
21	7.4				Y
22	7.4				Y
23	7.4				Y
24	7.4				Y
25	7.5				Y
26	7.5				Y
27	7.5				Y
28	7.5				Y
29	1.3				Y
30	7.5				Y
31	7.5				Y
lo = N	= Excu	rsion)	Total	N's	Ø

< <have< th=""><th>County: Linn</th><th>Agency: LINN COUNTY</th></have<>	County: Linn	Agency: LINN COUNTY					
minimums	<b>ENTRY POINT</b>						
been met for							
this day?	EP-A						
PWS ID 4100474							
LAWRENCE SUBDIVISION WTR ASSN							
Sample pe		ecember 2024 Month/Year					

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality Parameter(s) as set by State:	
pH 7.2	
Print Name: Jody Anthony Signature: Market Charles	
Date & Phone#: 1-24-25	
Send to DWP within 10 days after end of sampling period	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

Reference