

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	Day	рН	Alk	Phos	Other	Y/N	
76		Service participation (September				Y	
Γ	1 2 3	7.5				Ÿ	
ſ	3	7.5				Y	
	4	7.5				Y	
	5	7.5 7.5 7.5 7.5 7.5 7.9				Y	
	6	7.4				Y	
	7	7.4				Y	
	8	7.4	1			Y	
	9	7.4				Y	
	10	7.4				Y	
	10 11 12 13	7.4 7.4 7.4 7.4 7.4				Y	
L	12	7.4				Y	
L	13	7.4				Y	
	14	7.4				Y Y	
L	15	7.4				4	
L	16	7.4				Y	
L	17	7.4				4	
L	18 19	7.4				Y	
L	19	7.4 7.4 7.4 7.4				Y	
1	20	74				Y	
1	21	7.4				Y	
	22 23	7.4				Y	
	23	7.4				Y	
-	24	7.4				Y	
-	25	7.4				Y	
-	26	7.4				Y	
_	27	7.4				Y	
-	28	7.4				4	
_	29	7.7				Y	
-	30	7.4				Y	
	31	7.4				Y	
(No	(No = N = Excursion) Total N's						

< <have< th=""><th>County: Linn</th><th>Agency: LINN COUNTY</th></have<>	County: Linn	Agency: LINN COUNTY					
minimums	ENTRY	POINT					
been met for this day?	E	P-A					
PWS ID 4100474 LAWRENCE SUBDIVISION WTR ASSN							

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2
Print Name: Jody Anthony
Signature: Long Conthus
Date & Phone#: 2/7/25 (541) 990 9835
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/