

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1 2 3 4 5 6	7.4				Y
2	7.4				Y
3	7.4				V
4	7.4				Y
5	7.4				Y
6	7.4				Y
7	7.4				Y
8	7.4				Y
9	7.4				Y
10 11 12	7.4				Y
11	7.4				Y
12	7.4				4
13	7.4				LY
14	7.4				Y
13 14 15 16	7.4				Y
16	7.4				Y
17	7.4				Y
18	7.4		<b></b>		1
19	7.5				Y
20 21 22 23	7.5				1
21	7.5				Y
22	7.5				Y
THE RESERVE AND ADDRESS OF THE PERSON NAMED IN	7.5		<u></u>		Y,
24	7.6				Y
25	7.6				Y
26	7.6				Y
27	7.7				Y
28	7.6				4
29					
30	, -				
31					
10 = N	1 = Exc	cursion	)Tota	I N's	0

<<Have minimums been met for this day?

County: Linn

Agency: LINN COUNTY

## **ENTRY POINT**

EP-A

**PWS ID 4100474** 

LAWRENCE SUBDIVISION WTR ASSN

Sample period: \_\_

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2

Print Name: Jos Anth Signature: /

Date & Phone#: 3-10-25

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/