

Water Quality Parameter Monitoring Form  
**Lead & Copper Rule Corrosion Control**

Day	pH	Alk	Phos	Other	Y/N
1	7.5				Y
2	7.5				Y
3	7.5				Y
4	7.5				Y
5	7.5				Y
6	7.5				Y
7	7.5				Y
8	7.5				Y
9	7.5				Y
10	7.5				Y
11	7.5				Y
12	7.6				Y
13	7.6				Y
14	7.6				Y
15	7.6				Y
16	7.5				Y
17	7.5				Y
18	7.5				Y
19	7.6				Y
20	7.6				Y
21	7.6				Y
22	7.5				Y
23	7.5				Y
24	7.5				Y
25	7.5				Y
26	7.5				Y
27	7.5				Y
28	7.5				Y
29	7.5				Y
30	7.4				Y
31	7.4				Y

<<Have  
minimums  
been met for  
this day?

County: Linn Agency: LINN COUNTY

**ENTRY POINT**

**EP-A**

**PWS ID 4100474**

**LAWRENCE SUBDIVISION WTR ASSN**

**Sample period:** March / 2025  
Month/Year

**Number of excursions during this month:** 0

(Over 9 excursions in 6 months is a violation.  
Entry Point and Distribution excursions are  
cumulative). An 'excursion' is any day in which the  
water quality parameter(s) fall below the minimum  
set by the State.

Reference

**Minimum Water Quality  
Parameter(s) as set by State:**

pH 7.2

**Print Name:** Joe Anthony

**Signature:** [Signature]

**Date & Phone#:** 4/6/25 541-990-9835

Send to DWP within 10 days after end of  
sampling period

(No = N = Excursion) **Total N's** 0

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>