

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.3				Y
1 2 3 4 5 6 7	7.3 7.3 7.3 7.3				Y
3	73				Y
4	7.3				Y
5	7.3				Ý
6	7.3				Y
7	7.3				Y
8	7.3				Y
9	7.3 7.3 7.3 7.3 7.3 7.3 7.3 7.4 7.4 7.4 7.7 7.3 7.3				Ý
10 11 12 13	7.3				Y
11	7.3				Y
12	7.3				Y
13	7.3				Y
14	7.3				Y
15 16	7.3				Y
16	7-4			- Andreas	Y
17	7-4				Y
18 19 20 21 22	7.4				Y
19	7.4				Y
20	7.4				Y
21	7.3				Y
22	7.3				Y
23	7.3				Y
24	7,2	-			Y
25	702				Y
26	7.2				Y
27	7,4				Y
28	7.3				Y
29	7.3				Y
30	1,3				Y
31	7.3				Y
No = N = Excursion) <b>Total N's</b>					

County: Linn Agency: LINN COUNTY
Minimums been met for this day?
EP-A
PWS ID 4100474
LAWRENCE SUBDIVISION WTR ASSN
Sample period:
August / 2025
Month/Year

Number of excursions during this month:

Ø

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference	
Minimum Water Quality Parameter(s) as set by St	ate:
pH 7.2	
Print Name: Joe Anthony	
Signature: Org Curt (rule)	
Date & Phone# 9/8/25 59/	1-990-583

Send to DWP within 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period