

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

1 2 3	7.35		Phos				ave		
					7	! I	mums	County: Linn	Agency: REGION 1
	7.45				 	l I	n met for	ENTRY	POINT
	7.71	······			y	this	day?		A
4	7,41				ý			PWS ID 4	100493
5	7.24				Y		LYO		ATER DISTRICT
6	7-18				4			THE STATE OF THE S	211EK DISTRICT
7	7,13				37		Sample	noriodi Mess	20.24
8	7.60				Ÿ		Sample	period: <u>May</u>	onth/Year
9	7.78				7	į	·	1/1	Onun/Year
10	7.24				9				
4	7.41				\$/	Number of excursions during this month: O (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
12	7.34				Y				
	7.47				7				
$\overline{}$	7.38				5				
	7.16				9				
	7.30				4	5	tate.		
1	7-17				9				
	7.57				Υ		⊢Refer	епсе ———	
	7.1		 		У			EST I TOS	_
	7.65				7	Minimum Water Quality Parameter(s) as set by State:			
	7.57		-+		4		,	———	s set by State:
7 7 .	7.84							pH 7.1	j-
	7.36				र्दी				
25					7				
	7:57				7				·
27=	7.10				Ħ				
28	7-40			1	7		<u> </u>		
29 -	7.51				4	P	rint Name	: John F	marker T. II
30 7	1.62					S	ignature:	John 7 Mark	markert.II
	.66				_	D	ate: <u>5-31</u>	1-2024	5
) = N :	= Excu	rsion) '	Total	N's (1			P within 10 days	after end of

sampling period
DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (503) 731-4381 Website: www.dhs.state.or.us/publichealth/dwp/index.cfm