

vvater Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Dav	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>O that is a second of</th></have<>	O that is a second of	
1	7.63		_		V	minimums	County: Linn Agency: REGION 1	
1	7.53				Y Y	been met for	ENTRY POINT	
3	7.37		 		4	this day?	DP-A	
1/	7.67	*			757		PWS ID 4100493	
5	7.78			- ,	7	$\mathbf{L}\mathbf{Y}$	ONS MEHAMA WATER DÌSTRICT	
6	7.30				Y			
7	7.13			!	7	Samul	e period: <u>June</u> 2024	
8	7.14				5	Sample	Month/Year	
9	7.21				4	<u> </u>	. Worth Teal	
10	7.63				5			
u	7.69				3	Number of excursions during this month: <u>O</u>		
12	7.12				4	(Over 9 excursions in 6 months is a violation. Entry		
13	8.00				γ	Point and Distribution excursions are cumulative).		
14	7.38				Y	An 'excursion' is any day in which the water quality		
15	7.57				Y	parameter(s) fall below the minimum set by the		
16	7.50				Y	State.		
17	7.52				9			
18	7.58				X	⊢ <i>Re</i> .	ference	
19	7,26				y			
20	7.32				9		Minimum Water Quality	
21	7-10				<u>y</u>		Parameter(s) as set by State:	
22	7-85				9		pH 7.1	
23	7.66				Y			
24	7.69				¥			
25	8.34		<u> </u>		7			
26	7.40				Y		}	
27	7.22			·				
28	7.79		 	<u> </u>	Y	Print Na	me: John F Markert IL	
29	7.49				X	Signatur	1.	
30	7.41				X			
Date. Obig 1 dos								
(No = N = Excursion) Total N's Send to DWP within 10 days after end of sampling period								
					_	sampiiily	henon	

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381 Website: www.dhs.state.or.us/publichealth/dwp/index.cfm