

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

of numan services								
Day	pН	Alk	Phos	Sili	Y/N	< <have< th=""><th></th><th>County: Linn Agency: REGION 1</th></have<>		County: Linn Agency: REGION 1
	7.18				y	minimums	. 1	ENTRY POINT
2	7.14				S	been met this day?	101	PA
3	7.51				Y	uns day:		
4	7.40				Y	PWS ID 4100493		
5	7.24				4		LYO	NS MEHAMA WATER DISTRICT
6	7.51				4			
7	7.18				9	Sai	mple	period: January 3025
8	7.41				3			Month/Year
9	7.53		<u> </u>		5	<u> </u>		
10	7.61				A	Į	•	
11	7.57				1	Number of excursions during this month: $\underline{\mathscr{O}}$		
12	7.69	<u> </u>	ļ	<b> </b>	4			ursions in 6∢months is a violation. Entry
13	7.46	ļ	<u> </u>		7	Point and Distribution excursions are cumulative).  An 'excursion' is any day in which the water quality		
14	7.36	<del> </del>		-	7			
15	7,30		<del> </del>	<u> </u>	4	param State.	eter(s	s) fall below the minimum set by the
16	7:26				4	State.		
17	7.41		<del> </del>	<u> </u>	y			
18	7.61		-		17	Reference		
19	7.49		<del> </del>		3			Minimum Water Quality
20	7.30	<del>                                     </del>		<del> </del>	14	]		Parameter(s) as set by State:
77	7.39		-	<u> </u>	12			
72	7-46		<del> </del> -	<del> </del>	5			pH 7.1
21/	7.47	-			\(\sigma\)	]		}
25	7.48	<del></del>	<del> </del>	<del> </del>	4			
24	7.49				4			
27	7.31				4			
28	7-16				4	] `		
29	7.30				У	Print Name: John Marker I Signature: John Form S		
30	7.36				Ŋ	Signature: John 7 mm		
31	7.38				X	Date	: 1-	51-2025
(No = N = Excursion) Total N's						Send to DWP within 10 days after end of		

sampling period

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (503) 731-4381 Website: www.dhs.state.or.us/publichealth/dwp/index.cfm