## Entry Point Monitoring Form



## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/F
1	7.73	54.42			in a solena, a
2	7,62	54.42			
3	7.63				
4	7.14				
5	7.61				
6	7.56	gumin .			
7	7.54	54.42			
8		47.88			
9	7.57				
10	7,58				
11	758				
12	7.59				
13	7.57				
14	7.54	47,88			
	7,57				
16	7.55				
	7.53				
18	7,50				
19	7.53				
20	7.54				
21	7.55	17.88			
	7.54				
	7,52	4768			
24	7.62				
	7.52				
	7.57				
27	7,49				
28	7.51				
29	7.49				
30	7.51	4			
31	7,52				
io = N	= Exc	ursion)	Total	N's	05

< <have minimums been met for</have 	County: Tillamook Agency: REGION 1  ENTRY POINT					
this day?	EP-A					
PWS ID 4100556						
NETARTS WATER DISTRICT						
Sample pe	riod: <u>AUGUST 2023</u> Month/Year					

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

inimum Water Quality arameter(s) as set by State:
pH 7.4 Alk 40.0 (Alkalinity)

Print Name: DAVID Hancock	
Signature: Nand Manuff	_
Date & Phone#: 9/6/23 503-812-032	2
Send to DWP within 10 days after end of	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/